

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave.St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-006124**Date Inspected:** 29-Mar-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 645**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1845**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Wang Zhu/Zang Hai Tao**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Components**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Hiranch Patel, was present during the times noted above for observations relative to the work being performed.

**Segment 3AW to 3BW**

This QA inspector performed MT of Tack Weld Areas. This QA Inspector generated an MT report for this date.

The member is identified as OBG Components. The weld designations reviewed are as follows:

-(OBW-3A-004)

-(OBW-3A-002)

**Segment 3AW to 3BW**

This QA inspector observed the following work in progress:

FCAW welding of Segment weld joint of 3AW to 3BW. Weld numbers and Welders are identified as below.

ZPMC QC is identified as Zang Hai Tao and Wang Zhu. The welding variables recorded by QC appeared to comply with the Applicable WPS.

-(Weld # OBW-3A-004, Welder# 202841)

-(Weld # OBW-3A-002, Welder# 220069)

-(Weld # OBW-3A-002, Welder# 053609)

-(Weld # SEG013A-021, Welder# 220068)

-(Weld # SEG013A-031, Welder# 220067)

Joint Fit up Verified of Segment weld joint of 3AW to 3BW, Weld # OBW-3A-001. This QA inspector observed

---

## WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

that Root Opening recorded does not comply with the Applicable WPS. This QA inspector generated an Incident report for this date.

Unless otherwise noted, all observed on this date appeared to generally comply with applicable contract documents

### Summary of Conversations:

No relevant conversations.

### Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 150-0042-2372, who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Patel,Hiranch	Quality Assurance Inspector
<b>Reviewed By:</b>	Clifford,William	QA Reviewer

---